

How-To's

Juniper Recovery USB

Take a USB stick and plug it in a working device.

Run the **request system snapshot media usb partition** command.

When you have a snapshot of the working device on the USB stick, it can be plugged into the device that has the issue.

Run the **request system reboot media usb** command to verify if the snapshot is working on the device that has the issue.

Finally, you can save the snapshot via the **request system snapshot media internal partition** command.

The device should now work normally.

Unique solution ID: #1013

Author: Steve

Last update: 2016-03-23 16:18